



Corrugated Culvert Pipe with serious structural deterioration prior to lining.

**Severely deteriorated culvert
structurally rehabilitated
with the CIPP
Poly-Triplex® Liner System.**



Epoxy Resin applied to Liner prior to installation.



Poly-Triplex® Liner Curing (approx. 3 hours).

Brighton, CO

Corrugated Culvert Pipe
110 feet long under
4-lane divided highway
completely rehabilitated
in one day with the
Poly-Triplex Liner System
with no traffic disruption.

